

Site: Korkay (518014)




Fruehauf Tractor trailer box

This item is located in Broadalbin, Fulton County, New York.

For further information, contact

Payson long, P. E. Environmental Engineer I

Description	Class 1 Div 1 Fruehauf Tractor trailer box
Manufacturer	Fruehauf
Model #	1X-cd 7959-112-82
Condition	Made in 1988
Quantity	1
Condition	Used and Fair condition
Registration #	1H2V05322JE004000
Quantity	1




*More pictures available on request

Mixer

This item is located in Broadalbin, Fulton County, New York.


Description	Model GD Mixer
Manufacturer	Alsop Engineering company
Model #	1 080-8023-302-41-5027-054
Power source	120 volts/ 10 Amps
Condition	Used and good
Quantity	2



Composite carbon tank

This item is located in Broadalbin, Fulton County, New York.

Description	Fiberglass wound composite carbon tank
Max Temp.	120° F
Max Pressure	150 psi
Flow Rate	10 GPM
Model	180HP
Quantity	9 tanks
Condition	Used- good condition
Extra Info.	All 9 need carbon removal



Motor Starter


This item is located in Broadalbin, Fulton County, New York.

Description	Motor Starter
Model #	B7021
Phase	3
Voltage	460V
Condition	Unknown
Form No.	K1068
Quantity	1

Blower

This item is located in Broadalbin, Fulton County, New York.

Description	Rotary Lobe Blower
Manufacturer	Roots Division
Serial #	41524
Condition	Used - Excellent condition
Roots ID No.	865-110-020
Quantity	1





*some spare parts available

Soil vapor extraction Unit (SVE)

This item is located in Broadalbin, Fulton County, New York.



Description	Soil vapor extraction Unit (SVE)
Manufacturer	Encotech
Power required	460V
Extra details	1760 RPM , 7.5 hp, 2000LB vapor absorber
Max Pressure	8 PSIG
Condition	Used- Excellent condition
Quantity	1



Metering Pumps

This item is located in Broadalbin, Fulton County, New York.

Description	Metering pump
Manufacturer	Milton Roy
Model #	E-551
Condition	Used- Good condition
Voltage	115 V
Quantity	2



Chemical Tank Mixer


This item is located in Broadalbin, Fulton County, New York.

Description	Mixer
Manufacturer	Reliance electric
Power	90V (dc)
Details	3.8 amp 1/3hp
Condition	Unknown
Quantity	2

Transfer pump

This item is located in Broadalbin, Fulton County, New York.


Description	Transfer Pump
Manufacturer	Gola Gould's pumps co.(Seneca falls ,NY usa)
Model #	1stfrmao
Serial #	S/N2435172
Size	1x1 1/4-6
Date MFG	10-92
Motor, Power	208-230,460V,2HP
Condition	Used and good
Quantity	1



Heater/Boiler

This item is located in Broadalbin, Fulton County, New York.

Description	Boiler
Model	G100W
Manufacturer	HB Smith
Boiler Type	Natural gas and propane
Maximum working pressure	50 psi
Condition	Poor and used
Quantity	1



% LEL Monitor



This item is located in Broadalbin, Fulton County, New York.

Description	Safe TNet 100 single point combustible gas monitor
Model #	72-1301
Accessories	Junction box (model # 18-0205-01), junction box for remote pipe mounted sensor (model # 25-0125-01), remote pipe mounted sensor (model # 61-0106) , hexane gas calibration kit
Condition	Unknown
Quantity	1

Flow meters

This item is located in Broadalbin, Fulton County, New York.


Description	Water flow meter
Power Requirements	12 volt DC, 315 mA
Model #	P51530-P0
Serial #	2090875
Weight	1.8 Lbs
Condition	Used- good condition
Available quantity	3
Input Frequency range	5 to 200 Hz
Quantity	Approximately 3



Auto Dialer

This item is located in Broadalbin, Fulton County, New York.


Description	Chatterbox automatic dialing with remote monitoring
Model #	CB-8
Serial #	85262
Manufacturer	Remote Alarms And Controls - RACO
Condition	Used - Excellent condition
Quantity	1



Ventilation Unit

This item is located in Broadalbin, Fulton County, New York.


Description	Breidert Air Product Ventilation Unit
Model #	BDFE-12
Accessories	Wall collar, guard , manual intake louver
Condition	Used- Good Condition
Quantity	1



Valves

This item is located in Broadalbin, Fulton County, New York.

Description	Butterfly valves
Max Pressure	150 psi
Max Flow Rate	18,500 gpm
Max Temperature	250 °F
Condition	Good condition
Quantity	1



Emergency Eye Wash Station

This item is located in Broadalbin, Fulton County, New York.

Description	Haws portable Eye Wash Station
Manufacturer	Haws drinking faucet company
Model #	7500 portable eye wash
Condition	Unknown
Weight	Approximately 140 lbs.
Quantity	1

PARTS LIST			
MODEL	ITEM #	QTY	DESCRIPTION
w660	1	1	Eye Wash Assembly
	2	1	Mounting Bracket
	3	1	Package Bacteriostatic Additive
	4	1	Drain hose with barb fitting
	5	1	Test Record Tag

